quantity of dimension one (dimensionless quantity)

Quantity in the dimensional expression of which all the exponents of the dimensions of the base quantities are zero.

Source:
PAC, 1996, *68*, 957 *(Glossary of terms in quantities and units in Clinical Chemistry (IUPAC-IFCC Recommendations 1996))* on page 987